

Operation-Manual

THS30X Series (THS301/302/304/307)

Multifunction Temp-Humid Transmitter

Indoor / Duct / Remote / Outdoor





Table of Contents

I.	Security considerations	3
II.	Installation	4
III.	Option accessory	5
IV.	Connection	7
V.	Physical Quantity Measuring Range List	8
VI.	Display and LED instruction	8
VII.	Software and calibration operation step	9
VIII	. Inspection and maintenance	60



Security considerations

Please read this Specification carefully, prior to use of this, and keep the manual properly, for timely reference.

Solemn Statement:

This product can not be used for any explosion-proof area.

Do not use this product in a situation where human life may be affected.

eYc-tech will not bear any responsibility for the results produced by the operators!

Warning!!


- Installation and wiring must be performed by qualified personnel in accordance with all applicable safety standards.
- This product must be operated under the operating conditions specified in manual to prevent equipment damages.
- Please using the product under the ordinary pressure, or it will influence safe problem.
- This product must be operated under the operating condition specified in this manual to prevent equipment damages.
- This product must be operated under the normally atmospheric condition to prevent equipment damages.
- To prevent products damage, always disconnect the power supply from the product before performing any wiring and installation.
- All wiring must comply with local codes of indoor wiring and electrical installation rules.
- Please use crimp type terminal.
- To prevent personal injury, do not touch the moving part of product in operation.
- It may cause high humidity atmosphere during the product was breakdown. Please take safety strategy.




II. Installation

1. Indoor

Wall mount



Cover




2. Outdoor


Fixed board for wall type




Plastic flange



Installing Fitting thread



Radiation shield





III. Option accessory

1. Fixed type

Order code	Name	Desciption	Dimension
4415000022 Metal Flange		Material: Stainless Steel 304	#12.5mn #2.5mn #2.5mn #2.5mn #2.5mn #2.5mn
8203104015 Plastic flange (Standard)		Material: PC fire-proof class	#12m 14.59m 15.59m 15.59m 15.59m 15.59m
AS-HS-S Fixed board		Material: Stainless Steel 304	42.0mm 33.9mm 4.70mm 4.70mm 1.0mm 1.0mm
8203104014 Fixed board for wall type(Standard)		Material : SPCC	12.00mm 12.
8203104012 Fitting thread	Section 1	Material: Stainless Steel 304	24 mm



2. Filter

Order code	Name	Desciption	Dimension
8203104010 PC membrane filter		Material: PC fire-proof class+cotton filter Outside diameter: 12 mm Length: 32 mm	Common filtering effect Max. Temp.: 80°C
4425000013 SUS sintered filter		Material: SUS sintered filter Aperture: 40 µm Outside diameter: 12 mm Length: 38 mm	Resist pressure, pollution and corrodent Nice filtering ability Max. Temp.: 200°C
8203104011 Metal grid filter with mesh		Material: Metal grid filter with mesh Outside diameter: 12 mm Length: 32 mm	Common resisting pollution React quickly Endure high Temp. Nice ventilation Max. Temp.: 200°C
8203104013 PC membrane filter +Metal mesh		Material: PC fire-proof class+Metal mesh Outside diameter: 12 mm Length: 32 mm	Fitting in with high humidity environment Max. Temp.: 120°C


3. Radiation shield

Order code	Name	Desciption	Dimension
THSA-0304 Radiation shield		Material: UVPC+S.S.	0110 mm WW ESE WW W ESE all mm e16 mm 73.72 mm




IV. Diagram

1. Analog Diagram




2. RS-485 Diagram



When output of ordering code is RS-485(without analog), RS-485 diagram of default setting is M type.

3. Analog + RS-485 Diagram






V. Physical Quantity Measuring Range List

Physical quantity	THS301 Indoor	THS302 Duct	THS304 Remote (PVC cable)	THS307 Outdoor (Shield)	
Temperature(T)	0 50°C	- 40 + 80°C 0 100%RH - 40 + 60 dp°C -46 0 fp°C			
Humidity(H)	0 100%RH				
Dew point(D)	- 40 + 50 dp°C				
Frost point(F)	-46 0 fp°C				
Wet-bulb temp.(W)	0 50°C	0 80°C			
Vapor pressure(E)	0 123 mbar	0 473 mbar			
Mixture ratio(R)	0 86 g/kg	0 546 g/kg			
Absolute humidity(A)	0 82 g/m ³	0 290 g/m³			
Specific enthalpy(S)	0 273 kj/kg	0 1526 kj/kg			

※In addition to temperature and humidity, other physical quantities can be set by the UI software(for use with the RS-485 function)

VI. Display and LED instruction

1.1 LCM display




1.2 LED Indication

1. Power: LED P, Green light ON

2. RS-485: LED P, Red light ON

3. LED light position statement:






VII. Software and calibration operation step

Product calibration requires a standard device to perform	
6.1 Application Program statement	11
6.2 Setting RS-485connection	12
6.3 Scan RS-485 connection	15
6.4 Setting RS-485 ModBus Protocol	20
6.5 Display and save data	22
6.6 Choose parameter of Output	27
6.7 Temperature Calibration with two points	29
6.8 Humidity Calibration with two points	34
6.9 Temperature Calibration with signal points	39
6.10 Humidity Calibration with signal point	42
6.11 Restore factory setting of signal/two point(s)	45
6.12 Temperature Calibration with more points	47
6.13 Humidity Calibration with more points	53
6.14 Restore factory setting of more points	59




- 6.1 Application Program statement
- 1. Free installation program: THS UI_F19.exe
 - a. Operating System requirements: Above Windows XP SP2



2. Other application program requirements: Above Microsoft Office 2003




- 6.2 Setting RS-485connection
- 1. Connect product to PC via RS-485 cable
- 2. Execute "THS UI"
- 3. Click " Interface \rightarrow Config "






- 4. Select the corresponding values of com port as fallowing:
 - a. Port: Come Port
 - b. Baud Rate
 - c. Data Frame
 - d. RS-485
 - e. Station ID(Factory default 1)



5. Click "Apply " complete setup



- 6. Connect successfully
 - a. Show value and trend chart of Temperature and Relative Humidity
 - b. Show Open port, Read successful






6.3 Scan RS-485 connection


*Use scan function to connect when forgetting the connection information or having more facilities.

- (1) Connect the product to PC via RS-485 cable
- (2) Execute "THS UI"
- (3) Click "Interface → Config "






- (4) Select the corresponding values of com port as fallowing
 - a. Port:
 - b. RS-485
- (5) Click " Scan" to execute connection facilities






- (6) Scan connection facilities and set up
 - a. Select "Station ID"
 - b. Click "CLOSE AND EXPORT"






(7) Click "Apply"






- (8) Connect successfully
 - a. Show values and trend chat Temperature and Relative Humidity
 - b. Show Open port, Read successful






- 6.4 Setting RS-485 ModBus Protocol
 - (1) Setting RS-485 connection step as step 6.1
 - (2) Click "Setting"





- (3) Select Modbus Protocol parameter
 - a. Station ID: 1 ... 247
 - b. Baud Rate: 9600, 19200, 38400, 57600, 115200
 - c. Data Frame: None-8Bit-1Stop, None-8Bit-2Stop, Even-8Bit-1Stop, Even-8Bit-2Stop, Odd-8Bit-1Stop, Odd-8Bit-1Stop




- (4) Click "Apply"
- (5) Execute connection as step 6.2 or 6.3 again



6.5 Display and save data

(1) Show data: Click "Display"






(2) Icon function statements

Auto Scale

Clear Clear the chart records Chart Change the chart style Select the OUTPUT channel OUT1 Set line color chosen from OUTPUT Color Snap chart Snap Save the data measuring when the system start connecting Export before clinking the Export icon Y Title (ON) Show/Not show the statement of Y axis X Title (ON) Show/Not show the statement of X axis AxisY2 (ON) Show/Not show the statement of Y secondary axis Legend (ON) Show/ Not show chart Log Show/Not show measuring data (OFF) Adjust time range of X axis 1 Minute Adjust range of Y axis




- (3) Setting time interval of record
 - a. File → Log Interval
 - b. Select time interval of record






- (4) Save/Log measuring data
 - a. Log measuring range: Save the data measuring when the system start connecting before clinking the Export icon
 - a-1. Click Display → Export




- a-2. Appoint path and Key in file name \rightarrow save
- * If file name is some as the path name, the original file will be covered.







- b. Log measuring data: Log the data which is on from start or off
- b-1. Display →Log(OFF)



- b-1. Appoint path and Key in file name > save > Log(ON)
- X If file name is some as the path name, the original file will be covered.









6.6 Choose parameter of Output

(1) Click "Output"






- (2) Select relative parameters from Output1 and Output2
 - a. Output style
 - b. Responding time
 - c. Voltage or currant Output
 - d. Voltage or current analog range
 - e. Upper and Lower point of Output
- (3) Click "Apply"






- 6.7 Temperature Calibration with two points
 - (1) Calibrate upper point of temperature
 - a. Click "Calibration"






- b. Put the product in the temperature control box, and adjust the upper point of temperature (ex: 100°C)
- c. Wait the temperature of control box is becoming stable
- d. Click Temperature → UPPER POINT






- e. Input the reference temperature, then click "SET"
- f. That calibrating upper point temperature is done.






- (2) Calibrate lower point of temperature
 - a. Put the product in the temperature control box, and adjust the lower point of temperature (ex:0°C)
 - b. The difference temperature between Upper and Lower point must be at least 30°C.
 - c. Wait the temperature of control box is becoming stable
 - d. Click Temperature → LOWER POINT






- e. Input reference temperature, then click "SET"
- f. That calibrating lower point temperature is done.






- 6.8 Humidity Calibration with two points
 - (1) Calibrate Upper point of humidity
 - a. Click "Calibration"






- b. Put the product in the humidity control box, and adjust upper point of humidity (ex: RH 80%)
- c. Wait the humidity of control box is becoming stable.
- d. Click Relative Humidity \rightarrow UPPER POINT






- e. Input reference humidity, then click "SET"
- f. That calibrating upper point humidity is done






- (2) Calibrate humidity lower point
 - a. Put the product in the humidity control box, and adjust lower point of humidity (ex: RH 20%)
 - b. Wait the humidity of control box is becoming stable.
 - c. Click Relative Humidity \rightarrow LOWER POINT






- d. Input reference humidity, then click "SET"
- e. That calibrating lower point humidity is done






- 6.9 Temperature Calibration with signal points
 - (1) Click "Calibration"






- (2) Put the product in the temperature control box, and adjust the temperature point which you want to calibrate (ex: 50°C)
- (3) Wait the temperature of control box is becoming stable
- (4) Click Temperature → OFFSET POINT






- (5) Input the reference temperature, then click "SET"
- (6) That calibrating upper point temperature is done






6.10 Humidity Calibration with signal point

(1) Click "Calibration"






- (2) Put the product in humidity control box, then adjust the humidity point which you want to calibrate (ex: 50%RH)
- (3) Wait the humidity of control box is becoming stable
- (4) Click Relative Humidity → OFFSET POINT






- (5) Input reference humidity, then click "SET"
- (6) That calibrating signal point humidity is done






- 6.11 Restore factory setting of signal/two point(s)
 - (1) Restore factory setting temperature
 - a. Click "Calibration"
 - b. Click temperature \rightarrow RECALL FACTORY CALIB
 - c. Show "Restore Factory Temperature Calib OK, Write successful"
 - d. That restore temperature of factory setting is done






- (2) Restore humidity of factory setting
 - a. Click "Calibration"
 - b. Clock Relative Humidity → RECALL FACTORY CALIB
 - c. Show "Restore Factory Rel. Humidity Calib OK, Write successful"
 - d. That restore humidity of factory setting is done






- 6.12 Temperature Calibration with more points
 - Because of that the product has high accuracy and using this calibration way can influence linear
 accuracy, we do not suggest to use this calibration way.
 - (1) Click "Calibration"

Statement: The existing value is record of more points of calibrating which was executed by factory when operators log in Calibration page at the first time.






- (2) Put the product in the environment of temperature which you want to calibrate
- (3) Wait the environment of temperature is becoming stable
- (4) Retain the factory setting:
 - a. Input the value which you want to calibrate in the Temperature area (ex: 25°C)
 - a-1. Tunit [°C] Value which product shows
 - a-2. Tstd [°C] Standard calibration value
 - %1: Please enter calibration points in the blank, 10 points maximal
 - %2: The interval between two points should be 10°C above
 - ※3: Execute step 6 when you want to repeat the calibration points and factory setting points or the temperature is less than 10°C
 - b. Click Temperature \rightarrow WRITE





- (5) Delete factory setting:
 - a. Click Temperature → CLEAR(Clear data)
 - b. Click Temperature \rightarrow WRITE(Clear factory setting)





c. Input the value which you want to calibrate


c-1. Tunit[°C]: Value which product shows

c-2. Tstd[°C]: Standard value of calibration

※1: Please enter calibration points in the blank, 10 points maximal


%2: The interval between two points should be 10°C above

d. click Temperature → WRITE






- (6) Retain the part of factory setting:
 - a. Click left keyboard twice on the mouse on the factory setting which you want to delete
 - b. Click delete icon of Keyboard or right keyboard of mouse to clear data
 - c. Click Temperature → WRITE(Clear factory setting)





- d. Input the value which you want to calibrate
- d-1. Tunit[%]: Value which product shows
- d-2. Tstd[%]: Standard value of calibration
- e. click Temperature \rightarrow WRITE






6.13 Humidity Calibration with more points


1. Click "Calibration"

Statement: The existing value is record of more points of calibrating which was executed by factory when operators log in Calibration page at the first time.






- 2. Put the product in the environmental of humidity which you want to calibrate
- 3. Wait the environmental of humidity is becoming stable
- 4. Retain the factory setting:
 - a. Input the value which you want to calibrate in the Relative Humidity area
 - a-1. Hunit[%]: Value which product shows
 - a-2. Hstd[%]: Standard value of calibration
 - ★1.Please enter calibration points in the blank, 10 points maximal
 - %2. The interval between two points should be 10% above
 - ※3.Execute step 6 when you want to repeat the calibration points and factory setting points or the
 humidity is less than 10%
 - b. Click Temperature → WRITE






- 5. Delete factory setting:
 - a. Click Relative Humidity → CLEAR(Clear data)
 - b. Click Relative Humidity → WRITE(Clear factory setting)






- c. Input the value which you want to calibrate in the Relative Humidity area
- c-1. Hunit[%]: Value which product shows
- c-2. Hstd[%]: Standard value of calibration
- ¾1.Please enter calibration points in the blank, 10 points maximal
- %2. The interval between two points should be 10% above
- d. Click Relative Humidity → WRITE






- 6. Retain the part of factory setting:
 - a. Click left keyboard twice on the mouse on the factory setting which you want to delete
 - b. Click delete icon of Keyboard or right keyboard of mouse to clear data
 - c. Click Relative Humidity → WRITE (clear factory setting)






- d. Input the value which you want to calibrate in the Relative Humidity area
 - d-1. Hunit[%]: Value which product shows
 - d-2. Hstd[%]: Standard value of calibration
- e. Click Relative Humidity \rightarrow WRITE






- 6.14 Restore factory setting of more points
 - 1. Recall temperature of factory setting
 - a. Click "Calibration"
 - b. Click Temperature → RECALL
 - c. That restore more point's temperature of factory setting is done





- 2. Recall the factory setting of more points of humidity
 - a. Click "Calibration"
 - b. Click "Relative Humidity" → RECALL
 - c. That restore humidity of factory setting is done





VIII. Inspection and maintenance

1. Maintenance

Since this product is inspected and calibrated for high accuracy at the factory before shipment, no calibration on the installation site is necessary when this product is installed. For inspection and maintenance follow the instructions below:

a. Periodic inspection

Periodically inspect this product for its sensing accuracy, and clean the cover.

Set the period between inspections based on atmospheric dust and other contaminants in

b. Sensor maintenance

the installation environment.

Do not damage sensor surface during maintenance process.

c. Troubleshooting

If any problem occurs during operation, refer to the table below for appropriate solutions.

2. Troubleshooting:

Problem	Cleck items	Soluations
●No output	Disconnected wiring	Re-perform wiring
●Unstable output	Loose wiring	● crew on terminal tightly or replace
	● Power supply voltage	wires
	● Sensor damages	● Replace the sensor
•Slow response	● Moisture / condensation on the	• Remove the sensor and filter. Dry
to output	product	power-off state sensor in clean air
●Errow in output	● Check installed location	seasoning
	● Check dust and contamination	● Refer to the section
	on the sensor	● Cleaning the filter
		● Changing the filter
		● Calibrate
		 ■ Replace the sensor



Sustainable | Green | Professional

Temp. & Humid. / Dew Point / Air Velocity & Volume / Flow / Pressure

Measuring Specialist



Tel.: 886-2-8221-2958 Web: www.eyc-tech.com e-mail: info@eyc-tech.com

www.eyc-tech.com